

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 312598



Photo #1983 from entrance to location.



Photo #1570 from inspection #699801478 conducted on 7/21/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 312598



Photo #1981 Multiple places with weeds and debris on location.



Photo #1982 Secondary containment not adequate weeds growing inside tank containment.