

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/25/2020

Submitted Date:

10/05/2020

Document Number:

693700605**FIELD INSPECTION FORM**
 Loc ID 424707 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10503Name of Operator: RED HAWK PETROLEUM LLCAddress: 575 N DAIRY ASHFORD STE 201City: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Boyd, William		wboyd@pedevco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424715	WELL	PR	08/01/2017	OW	123-34144	Planck 1-14H	EI
470960	SPILL OR RELEASE	AC			-	Planck 1-14H	EI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Stained soil at wellhead from inspection #696300729 has been removed. However oil from drum inside tank secondary containment is present; condensate/oil is present around flare and ECD

Corrective Action:

Dispose of oily waste in accordance with Rule 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 11/05/2020Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	424715	Type:	WELL	API Number:	123-34144	Status:	PR	Insp. Status:	EI
Facility ID:	470960	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Environmental****Spill/Remediation:**

Comment: [Spill #470960 was reported January 23, 2020 for failed gasket on treater. COGCC did not observe leaking treater or impacted material at the time of inspection.](#)

Corrective Action: [Submit Form 19 Supplemental Report with soil disposal manifests, confirmation soil sample analytailca data, and maps showing soil sample locations.](#)

Date: 12/05/2020

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700606	Drum and staining inside secondary containment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262121</a>
693700607	Impacted material around flare	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262122">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262122</a>
693700608	Condensate at base of flare	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262123">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262123</a>
693700609	Blowdown near ECD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262124">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5262124</a>