



40.04598, -108.57605, 6901.1ft, 45°
10/05/2020 12:48:05 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Calamity Ridge 4401D A23 1N100 API: 05-103-10561
Inspection: 700403759



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Calamity Ridge 4401D A23 1N100 API: 05-103-10561
Inspection: 700403759



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Meter building.

Calamity Ridge 4401D A23 1N100 API: 05-103-10561
Inspection: 700403759



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank secondary containment liner.

Calamity Ridge 4401D A23 1N100 API: 05-103-10561
Inspection: 700403759



40.04609, -108.57597, 6893.9ft, 310°
10/05/2020 12:47:14 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tank secondary containment liner.

Calamity Ridge 4401D A23 1N100 API: 05-103-10561
Inspection: 700403759



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Valve can.

Calamity Ridge 4401D A23 1N100 API: 05-103-10561
Inspection: 700403759



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Well head.

Calamity Ridge 4401D A23 1N100 API: 05-103-10561
Inspection: 700403759

