

Inspection Photos

ID: 321225

Operator: THOMAS L SPRING LLC

Inspection Date: 9/24/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing west along the access road. The access road has not been reclaimed and there is undesirable weeds along the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing north along the access road. The access road has not been reclaimed and there is undesirable weeds along the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 3. Facing northwest toward the location. There is undesirable weeds (Kochia) throughout the entire location which has grown to 4-6 feet tall.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 4. There is equipment that remains at the location that has not been removed. The weeds have grown around the equipment and are a fire hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 5. Facing southwest at the location. The meter shed and tank battery remains. All equipment should have been removed within 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 6. The locastion sign is faded and not legibile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 7. Facing toward the tank battery. The weeds are thick and overgrown that the surface of the location was not visible. It is unknown if there is secondary containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 8. Facing northeast toward the location. The surrounding field has been mowed however the entire location is completely overgrown with Kochia.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020

Inspection Photos



Photo 9. Facing west toward the location. The surrounding field has been mowed however the entire location is completely overgrown with Kochia.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:321225 | Date: 9/24/2020