

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2020

Submitted Date:

10/06/2020

Document Number:

699700199**FIELD INSPECTION FORM**Loc ID 322299 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections
Fischer, Alex		alex.fischer@state.co.us	
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	All Inspections
Hale, Steve		shale@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210185	WELL	TA	07/01/2019	GW	045-05080	SOUTH CANYON-FEDERAL 4	EI

General Comment:

On September 29, 2020 COGCC Environmental Staff (John Heil) conducted an environmental field inspection of UTAH GAS OP LTD DBA UTAH GAS CORP (Utah Gas operator #10539) South Canyon Fed 4 Location ID 322299.

Operator personnel were on location drilling and installing ground water monitoring wells to address impacts from Pit ID 111716.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	Various sized unmarked risers (wellhead and separator). Flow line risers not LO/TO or marked are considered unused equipment. Comply with Rule 603.f.		
Corrective Action:	For unused, unmarked flow line risers: 24 hours to lock out tag out. 30 days to remove riser.		Date: <u>10/07/2020</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: <input type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Environmental**Spill/Remediation:**

Comment: [See Remediation #10464 for more information.](#)
 A solar powered soil vapor extraction (SVE) system related to Remediation #10464 was observed on location. Four new ground water monitoring wells were being installed to delineate ground water impacts from the historical pit (Pit ID 111716). The impacts are located approximately 20 feet south of an arroyo, no surface water was observed at time of inspection.

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700200	20200929 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5263506