

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2020

Submitted Date:

09/30/2020

Document Number:

699302719

FIELD INSPECTION FORM

Loc ID 417941 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 417934 | WELL | PR | 07/01/2020 | OW | 123-31791 | DECHANT X 08-09 | PR |

General Comment:

(This area is currently blank for general comments.)

| Location | | | |
|--|--|--------|-------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | well is in middle of an alfalfa field | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | due to well being in an alfalfa field weeds have overgrown and need to be addressed now that there is access | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | barbless wire | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | barbless wire | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Ag fence | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|-----------------------------------|---|--|------------------|
| Type: Gas Meter Run | # 1 | | |
| Comment: | card in meter house indicates that calibration is not current | | |
| Corrective Action: | comply with Rules 328/329 measurement of oil and gas. | | Date: 12/30/2020 |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | appears to be plumbed to surface | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 4 | | |
| Comment: | automation | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER | 1 | 100 BBLs | BV CONCRETE | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 60 bbl |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-------------------------------------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | shares containment with crude tanks | | | |
| Corrective Action: | | | | Date: |

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

Inspected FacilitiesFacility ID: 417934 Type: WELL API Number: 123-31791 Status: PR Insp. Status: PR**Producing Well**Comment: [PR, Form 04 other Doc # 402374363 submitted on 4-17-2020 and is in process and From 42 \(PR\) Doc # 402436681 was submitted on 7-2-2020 and i approved.](#)

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Wednesday 9/30/2020 at approximately 1420 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:

Dechant X08-09 at API #05-123-31791 in Weld County Colorado.

While there, I observed a wellsite and tank battery. [PR, Form 04 other Doc # 402374363 submitted on 4-17-2020 and is in process and From 42 \(PR\) Doc # 402436681 was submitted on 7-2-2020 and is approved.](#)

During this inspection the following possible compliance issue was observed: 328/329 measurement of oil/gas. Card in meter house indicates that calibration is not current. CA date 12-30-2020 see photos 7 & 8.

Due to well being in an alfalfa field weeds have overgrown and need to be addressed now that there is access
 See attached photos.
 Location is dry, weather is clear.
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

revasr

09/30/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402501039 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5260124 |
| 699302720 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5260121 |