

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/29/2020

Submitted Date:

09/29/2020

Document Number:

699801854

FIELD INSPECTION FORM

Loc ID: 311750
Inspector Name: De Paolo, Corey
On-Site Inspection:
2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278011	WELL	PR	09/05/2007	GW	077-08899	HELLS GULCH FEDERAL 26-3	PR
278012	WELL	PR	02/01/2015	GW	077-08898	HELLS GULCH FEDERAL 26-4	PR
290044	WELL	PR	10/01/2014	GW	077-09279	HELLS GULCH FED. 26-3B	PR
290045	WELL	PR	01/01/2011	GW	077-09278	HELLS GULCH FED. 26-3A	PR
290047	WELL	PR	07/09/2014	GW	077-09276	HELLS GULCH FED. 26-5A	PR
290048	WELL	PR	10/25/2008	GW	077-09275	HELLS GULCH FED 26-4C	PR
290049	WELL	PR	05/23/2014	GW	077-09274	HELLS GULCH FED. 26-4B	PR
290050	WELL	PR	02/01/2015	GW	077-09273	HELLS GULCH FED. 26-4A	PR
290051	WELL	PR	02/01/2015	GW	077-09272	HELLS GULCH FED. 26-3C	PR

General Comment:

[COGCC Inspection Report Summary](#)

On Tuesday 9/29/20 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Hells Gulch Federal /26-6 Pad, Location #311750 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Berm at base of SE cut slope has eroded and migrated into adjacent ditch. See photo #1944 and #1945. Waddles on SW corner of the cut slope have been covered by sediment migration. See photo #1946 and #1947.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	
Equipment:			
Type:	Vertical Heated Separator	# 4	corrective date
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks by wellheads		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	278011	Type:	WELL	API Number:	077-08899	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	278012	Type:	WELL	API Number:	077-08898	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	290044	Type:	WELL	API Number:	077-09279	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	290045	Type:	WELL	API Number:	077-09278	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	290047	Type:	WELL	API Number:	077-09276	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	290048	Type:	WELL	API Number:	077-09275	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	290049	Type:	WELL	API Number:	077-09274	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	290050	Type:	WELL	API Number:	077-09273	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				

Facility ID: 290051 Type: WELL API Number: 077-09272 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms	Fail					
Waddles	Fail					
Gravel						
		Sediment Traps				
Check Dams						
		Gravel				
Sediment Traps						
		Check Dams				
		Waddles				
Culverts						
Ditches						
		Ditches				
		Berms				

Comment: Berm at base of SE cut slope has eroded and migrated into adjacent ditch. See photo #1944 and #1945. Waddles on SW corner of the cut slope have been covered by sediment migration. See photo #1946 and #1947.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations. Properly maintain BMP's.

Date: 10/14/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402500263	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259347
699801855	Photos for Insp. #699801854	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259339