

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /14SESE

Location ID: 312464



Photo #1986 from entrance to location.



Photo #1081 from inspection #699800998 conducted on 4/28/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /14SESE

Location ID: 312464



Photo #1987 Unused equipment.