

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2020

Submitted Date:

10/06/2020

Document Number:

699801884**FIELD INSPECTION FORM**Loc ID 312464 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|----------------------------------|---------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , BLM | | jbyers@blm.gov | |
| Graves, Jim | | mrinc20@maralexinc.com | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Jordan, Reid | | maralextechjr@gmail.com | |
| , Engineering | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 221691 | WELL | SI | 09/01/2017 | GW | 077-08293 | USA 1-14 HC | SI |

General Comment:**COGCC Inspection Report Summary**

On Tuesday 10/6/20 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC USA-69S98W /14SESE, Location #312464 in Mesa County Colorado.

Refer to document #699800998 inspection conducted on 4/28/20. Not all corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Unused equipment. See photo #1080 and #1987 with a previous corrective action date of 7/28/20. MIT required on well. With a previous corrective action date of 7/28/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

| Location | | | | |
|--|--|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | 911 | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | UNUSED EQUIPMENT | | | |
| Comment: | Unused equipment. See photo #1080 and #1987 | | | |
| Corrective Action: | Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove meter run from location. | | | Date: 07/28/2020 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Pipe rail fence | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| | | | | corrective date |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Venting: | | | | |
| Yes/No | NO | | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

Inspected FacilitiesFacility ID: 221691 Type: WELL API Number: 077-08293 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Well last produced prior to 1999. No MIT on record.Corrective Action: All temporarily abandoned wells shall pass a mechanical integrity test. Preform MIT on well.Date: 07/28/2020

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 699801885 | Photos for Insp. #699801884 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5263833 |