

Inspection Photos

API: 071-07560

Operator: TIMBER CREEK OPERATING

Inspection Date: 10/1/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 10/1/2020

Inspection Photos



Photo 1. There is vehicle rutting along the road traveling to the location. The road needs to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 10/1/2020

Inspection Photos



Photo 2. Facing southeast along the access road. There is a low spot in the road where stormwater appears to accumulate. This area needs to be repaired to allow proper drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 10/1/2020

Inspection Photos



Photo 3. Likewise to previous photo. There is a low spot in the road where stormwater appears to accumulate where vehicles are widening the road to avoid this area. This area needs to be repaired to allow proper drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 10/1/2020

Inspection Photos



Photo 4. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 10/1/2020

Inspection Photos



Photo 5. facing toward separator engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 10/1/2020

Inspection Photos



Photo 6. There is oil stained soils around the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 10/1/2020