

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2020

Submitted Date:

10/07/2020

Document Number:

700701657

FIELD INSPECTION FORM

 Loc ID 423439 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10531
 Name of Operator: GRIZZLY OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 16 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412841	WELL	PR	07/21/2011	GW	045-18667	MILLER 33D-6-791	PR
412843	WELL	PR	07/21/2011	GW	045-18666	MILLER 33C-6-791	PR
412844	WELL	PR	06/06/2011	GW	045-18665	MILLER 33B-6-791	PR
412845	WELL	PR	09/01/2019	GW	045-18664	MILLER 33A-6-791	PR
412846	WELL	PR	07/21/2011	GW	045-18663	MILLER FEDERAL 23D-6-791	PR
412847	WELL	PR	06/06/2011	GW	045-18662	MILLER FEDERAL 23C-6-791	PR
412848	WELL	PR	06/06/2011	GW	045-18661	MILLER FEDERAL 23B-6-791	PR
412849	WELL	PR	07/20/2011	GW	045-18660	MILLER FEDERAL 24D-31-691	PR
412850	WELL	PR	07/20/2011	GW	045-18659	MILLER FEDERAL 24C-31-691	PR
412853	WELL	PR	07/01/2019	GW	045-18657	MILLER FEDERAL 24A-31-691	PR
412910	WELL	PR	07/21/2011	GW	045-18658	MILLER FEDERAL 24B 31-691	PR

General Comment:

COGCC Inspection Report Summary
 On Wednesday 10/7/20 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Miller 10, at Location # 423439 in Garfield county Colorado.
 While there, I observed normal production operations. All meters have been calibrated on location within the past year. All C/A(s) from previous inspection document # 700701619 have been completed.
 This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Equipment:			
Type: Bird Protectors	# 8		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	chemical tanks at well heads		

Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	412841	Type:	WELL	API Number:	045-18667	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412843	Type:	WELL	API Number:	045-18666	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412844	Type:	WELL	API Number:	045-18665	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412845	Type:	WELL	API Number:	045-18664	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412846	Type:	WELL	API Number:	045-18663	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412847	Type:	WELL	API Number:	045-18662	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412848	Type:	WELL	API Number:	045-18661	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412849	Type:	WELL	API Number:	045-18660	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 412850 Type: WELL API Number: 045-18659 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 412853 Type: WELL API Number: 045-18657 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 412910 Type: WELL API Number: 045-18658 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps		Ditches				
Berms		Check Dams				
Ditches		Culverts				
Rip Rap		Sediment Traps				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701662	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264382