

Inspection Photos  
Operator: Logos Operating  
API: 067-05709  
Date: 10/1/2020



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the southern project area from the northeastern corner facing westward. Vegetation appears to be progressing here largely with rubber rabbitbrush.





Photo 3. View of the eastern project area from the northeastern corner facing southward.





Photo 4. View of reference area vegetation comprised of dense rubber rabbitbrush with understory of grasses such as sand dropseed and western wheatgrass.



Photos 5/6. Closed gate coming in (left) and leaving (right). Vehicle outside of gate as inspector walked into site.