

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2020

Submitted Date:

10/07/2020

Document Number:

696302544**FIELD INSPECTION FORM**Loc ID 327811 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10017Name of Operator: CHACO ENERGY COMPANYAddress: P O BOX 1587City: DENVER State: CO Zip: 80201**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Matt Nelson	303-981-3840	matt@chacoenergy.com	
Nelson, Kurt	(303) 744-1480	kurt@chacoenergy.com	All Inspections
Nelson, Alan	(405)942-3751/10017	chaco@swbell.net	Production Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247385	WELL	PR	06/01/2020	OW	123-15182	WELD COUNTY-KINDT 1	PR

General Comment:[This is a Follow-Up Inspection to FIR 696302381 and FIRR 402492941](#)

Location				
Lease Road:				
Type	Main			
comment:	Lease Road mowed			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Adequate - Skim Tank now has proper Labels			
Corrective Action:			Date:	
Type	BATTERY			
Comment:	Adequate			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<input type="text"/>			Date: _____
Corrective Action:	<input type="text"/>			
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds have been removed and mowed from location			
Corrective Action:			Date:	
Type	OTHER			
Comment:	Stained Soil at Pumping Unit has been removed			
Corrective Action:			Date:	
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	Barbed Wire has been installed			
Corrective Action:			Date:	
Type	SEPARATOR			
Comment:	Barbed Wire has been installed			
Corrective Action:			Date:	
Equipment:				
Type: Vertical Separator	# 1			corrective date
Comment:	<input type="text"/>			

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.590300,-103.731770
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms have been repaired and Barbed Wire fence installed around Tank Battery			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	247385	Type:	WELL	API Number:	123-15182	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Seeding				

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: _____ Lat: 40.590300 Long: -103.731770

Reference Point: SE Other: _____ Length: 30 Width: 25

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 09/22/2020 at approximately 12:54, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Chaco Energy Company, Weld County Kindt 1, Location #327811 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>Weeds have been removed and Lease Road has been mowed.</p> <p>Stained Soil at the Pumping Unit - Wellhead and Gas Engine has been removed</p> <p>Berms around Crude Tank and Heater Treater knocked down by Cattle, have been repaired and Barbed Wire Fence has been installed.</p> <p>Skim Tank now has Capacity and NFPA Labels.</p> <p>This is a summary of the Inspection Report.</p>	petrie	10/07/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302545	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264545