

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2020

Submitted Date:

10/08/2020

Document Number:

690102110**FIELD INSPECTION FORM**Loc ID 425737 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425743	WELL	SI	07/01/2020	OW	123-34505	GUTTERSEN C 33-33D	EG
425745	WELL	SI	07/01/2020	GW	123-34506	GUTTERSEN C 33-31D	EG
425746	WELL	SI	07/01/2020	GW	123-34507	GUTTERSEN C 33-32	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos Uploaded

Inspected Facilities

Facility ID: <u>425743</u>	Type: <u>WELL</u>	API Number: <u>123-34505</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>425745</u>	Type: <u>WELL</u>	API Number: <u>123-34506</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>425746</u>	Type: <u>WELL</u>	API Number: <u>123-34507</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
Variance: No Age: 10-15 Yrs Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made:
Coatings: Yes External H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Wells (Gutterson C 33-33D, 31D, 33-32) are Shut in; OOSLAT observed on off location flowline valves at wellhead and inlet to heated horizontal separator. The shared facility/ battery services the (3) wells; No Noble Energy or contract personnel were on location at the time of this field inspection. No CA's were identified during this field inspection.

Corrective Action: **Date:**

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102111	Signage and tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264938
690102112	Gutterson C 33-33D wellhead; OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264939
690102113	OLF's inlet at heated horizontal separator; OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264940