

Inspection Photos
Operator: Hilcorp Energy
API: 067-08171
Date: 10/7/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with smooth brome, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of revegetation within the western and northwestern project area, facing southwestward.



Photo 4. View of reference area vegetation comprised of gambel oak shrubland in a post-fire vegetative condition with other shrubs such as mountain mahogany, serviceberry as well as grasses and forbs such as squirreltail and Colorado rubberplant.