

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**API: 067-08641**  
**Date: 10/7/2020**



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward.



Photo 3. View of the southern project area from the southeaster corner facing westward.



Photo 4. View of reference area vegetation comprised of gambel oak shrubland in a post-fire vegetative condition with other shrubs such as mountain mahogany, serviceberry as well as grasses and forbs such as squirreltail and Colorado rubberplant.