

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2020

Submitted Date:

10/01/2020

Document Number:

699501738

FIELD INSPECTION FORM

Loc ID: 318596 Inspector Name: MEDINA, JUSTIN On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241696	WELL	PR	02/01/2020	OW	123-09485	SUCKLA-BROWN UNIT 17	PR
475276	OFF-LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475277	OFF-LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475278	OFF-LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475279	OFF-LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475280	OFF-LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475281	OFF-LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475282	OFF-LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Stained soil by flowline manifold appears to be leaking.see pictures 1,2

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 10/01/2020

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: electric motor

Corrective Action:

Date:

Type: Bird Protectors

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: Calibrated this year

Corrective Action:

Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>241696</u>	Type:	<u>WELL</u>	API Number:	<u>123-09485</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>475276</u>	Type:	<u>OFF-</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>
Facility ID:	<u>475277</u>	Type:	<u>OFF-</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>
Facility ID:	<u>475278</u>	Type:	<u>OFF-</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>
Facility ID:	<u>475279</u>	Type:	<u>OFF-</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>
Facility ID:	<u>475280</u>	Type:	<u>OFF-</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>
Facility ID:	<u>475281</u>	Type:	<u>OFF-</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>
Facility ID:	<u>475282</u>	Type:	<u>OFF-</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>

Producing Well			
Comment:	<u>PR</u>		
Corrective Action:		Date:	

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On 10/2/20 at approximately 1330 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Suckla Brown Unit 17 Company Name- KPK API- 05-123-09485 In Weld County Colorado. While there, I observed Producing well During this inspection the following possible compliance issues were observed: Stained soil by flowline manifold appears to be leaking see pictures 1,2 Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. 10/1/20 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection I contacted emergency number on wellsite and informed KPK representative of possible issue on location. This is a summary of inspection report.</p>	medinaj	10/01/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501739	Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5266308