

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/22/2020

Submitted Date:

10/03/2020

Document Number:

688308588

**FIELD INSPECTION FORM**
 Loc ID 420585 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96340

Name of Operator: WIEPKING-FULLERTON ENERGY LLC

Address: 106 GLENMOOR LN

City: ENGLEWOOD State: CO Zip: 80113

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Boone, Linda	(720) 271-8605	LDBoonePar@aol.com	All Inspections
Shalberg, Greg	(719) 688-3547	gregshalberg@aol.com	
Herian, Tim	(316) 655-9200	therian1@cox.net	All Inspections
Halde, Kerry	(719) 340-0329	haldeoil@hotmail.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159422	UIC DISPOSAL	AC	07/03/2013		-	NAPALI 1 DISPOSAL WELL	AC

**General Comment:**

Housekeeping Inspection at Tank Battery

Staining inside tank containment and oil staining on north tank from thief hatch.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	719-340-0329		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Leaks at piping and thief hatch on tank (see attached photos).		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 11/06/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 159422 Type: UIC API Number: - Status: AC Insp. Status: AC**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402502829	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261702">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261702</a>
688308691	Wiepking-Fullerton Napali 1 Tank Battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261700">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261700</a>