

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2020

Submitted Date:

10/07/2020

Document Number:

700403773**FIELD INSPECTION FORM**Loc ID 316341 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 200502Name of Operator: 31 OPERATINGAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone        | Email                    | Comment |
|---------------|--------------|--------------------------|---------|
| Thompson, Bud |              | BLThomps@BLM.gov         |         |
| Freeman, Kris | 254-727-0435 | kfreeman@31operating.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 267099      | WELL | PR     | 04/09/2003  | GW         | 103-10296 | ANT HILL UNIT 18-43 | PR          |

**General Comment:**

A follow up inspection of FIR document 700402938 dated 8-17-2020.

The following compliance issues are uncompleted:

1) Weeds on location. Photos 1, 2, 3. Complete by 9-18-2020.

This is a summary of inspection report 700403773.

**Location**Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | CONTAINERS           |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                          |       |            |
|--------------------|--------------------------|-------|------------|
| Type               | WEEDS                    |       |            |
| Comment:           | Weeds on location.       |       |            |
| Corrective Action: | Comply with Rule 603.f . | Date: | 09/18/2020 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                           |     |       |                 |
|---------------------------|-----|-------|-----------------|
| Type: Plunger Lift        | # 1 |       | corrective date |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Gas Meter Run       | # 1 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Deadman # & Marked  | # 4 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Ancillary equipment | # 1 |       |                 |

|  |     |       |
|--|-----|-------|
| Comment: <a href="#">Chemical container.</a> |     | Date: |
| Corrective Action:                           |     | Date: |
| Type: Horizontal Heated Separator            | # 1 |       |
| Comment:                                     |     | Date: |
| Corrective Action:                           |     | Date: |
| Type: Bird Protectors                        | # 2 |       |
| Comment:                                     |     | Date: |
| Corrective Action:                           |     | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         | Date:  |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     |                     | Adequate    |
| Comment:           |          |                     |                     | Date:       |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         | Date:  |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     |                     | Adequate    |
| Comment:           |          |                     |                     | Date:       |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|        |  |
|--------|--|
| Yes/No |  |
|--------|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 267099         | Type: WELL | API Number: 103-10296 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    | PR         |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       | Material Handling And Spill Prevention |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402505343    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264197">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264197</a> |
| 700403774    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264189">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264189</a> |