

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate X 3		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Ag fence X 3		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 3		corrective date
Comment:	automation		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	all appear to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	445095	Type:	WELL	API Number:	123-42882	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
Facility ID:	445097	Type:	WELL	API Number:	123-42884	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
Facility ID:	445100	Type:	WELL	API Number:	123-42886	Status:	XX	Insp. Status:	ND
Facility ID:	445101	Type:	WELL	API Number:	123-42887	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR, Form 04 other Doc # 402475856 submitted on 8-26-2020 and is approved & Form 42(PR) Doc # 402475148 submitted on 8-26-2020 and is approved.								
Corrective Action:								Date:	

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10/14/2020 at approximately 1120 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Noble Energy location:</p> <p style="text-align: center;">Shadow A26-651 Pad at Location #445094 in Weld County Colorado.</p> <p>While there, I observed a wellsite. The Shadow A26-651 has not been drilled, The Shadow A26-646, The Shadow A26-637 & The Shadow A26-632 are PR. During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	10/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302758	wellsite pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5270639