

TEP
RMV 39-16
Location # 335788



location



location

TEP
RMV 39-16
Location # 335788



Oct 14, 2020 at 11:20:55 AM
+39.528416, -107.900583 ±4.74m
COGCC

location



Oct 14, 2020 at 11:21:42 AM
+39.528416, -107.900583 ±4.74m
COGCC

Signage is in need of repair

TEP
RMV 39-16
Location # 335788



Oct 14, 2020 at 11:21:28 AM
+39.528478, -107.900466 ±4.73m
COGCC

location



Oct 14, 2020 at 11:23:06 AM
+39.528443, -107.899950 ±4.79m
COGCC

South side of road at entrance to location sediment coming through culvert.

TEP
RMV 39-16
Location # 335788



Erosion undercutting of BMP's



North side of road at entrance to location sediment going through culvert.

TEP
RMV 39-16
Location # 335788



North side of road at entrance to location sediment going through culvert.



Erosion undercutting of BMP's

TEP
RMV 39-16
Location # 335788



Erosion undercutting of BMP's



Erosion undercutting of BMP's

TEP
RMV 39-16
Location # 335788



Sediment migration



Sediment migration

TEP
RMV 39-16
Location # 335788



Riling and sediment migration



Sediment migration