

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2020

Submitted Date:

10/15/2020

Document Number:

700701696

FIELD INSPECTION FORM

Loc ID 335175 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211145	WELL	PR	02/15/1995	GW	045-06904	CLOUGH RMV-10-22	PR
281515	WELL	PR	08/01/2006	GW	045-11477	CLOUGH RWF 322-22	PR
281517	WELL	PR	07/30/2006	GW	045-11478	CLOUGH RWF 422-22	PR
281518	WELL	PR	07/30/2006	GW	045-11479	CLOUGH RWF 522-22	PR
281521	WELL	PR	07/30/2006	GW	045-11480	CLOUGH RWF 32-22	PR

General Comment:[COGCC Inspection Report Summary](#)

On Thursday 10/15/20 at approximately 1030, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 10-22, at Location # 335175 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	500 gallon methanol tank at separators		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLs	STEEL AST		,
Comment:	80 bbl tanks in shared containment with condensate tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>211145</u>	Type:	<u>WELL</u>	API Number:	<u>045-06904</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>281515</u>	Type:	<u>WELL</u>	API Number:	<u>045-11477</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>281517</u>	Type:	<u>WELL</u>	API Number:	<u>045-11478</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>281518</u>	Type:	<u>WELL</u>	API Number:	<u>045-11479</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>281521</u>	Type:	<u>WELL</u>	API Number:	<u>045-11480</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				
Berms		Check Dams				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701703	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271614