

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2020

Submitted Date:

10/15/2020

Document Number:

700701698

FIELD INSPECTION FORM

 Loc ID 335215 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210473	WELL	PR	08/02/2001	GW	045-06229	CLOUGH 115	PR
262716	WELL	PR	08/10/2002	GW	045-08048	CLOUGH RMV 162-22	PR

General Comment:[COGCC Inspection Report Summary](#)

On Thursday 10/15/20 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Clough 115, at Location # 335215 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
-----------------	--	--	--

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210473 Type: WELL API Number: 045-06229 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 262716 Type: WELL API Number: 045-08048 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701705	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271616