

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2020

Submitted Date:

10/01/2020

Document Number:

699501738

FIELD INSPECTION FORMLoc ID 318596 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241696	WELL	PR	02/01/2020	OW	123-09485	SUCKLA-BROWN UNIT 17	PR
475276	OFF- LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475277	OFF- LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475278	OFF- LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475279	OFF- LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475280	OFF- LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475281	OFF- LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC
475282	OFF- LOCATION FLOWLINE	AC	04/13/2020		-	Wellhead Line 10NWSE	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Stained soil by flowline manifold appears to be leaking.see pictures 1,2

Corrective Action:

Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 10/01/2020

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: electric motor

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: Calibrated this year

Corrective Action:

Date:

Type: Bird Protectors

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241696	Type: WELL	API Number: 123-09485	Status: PR	Insp. Status: PR
Facility ID: 475276	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC
Facility ID: 475277	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC
Facility ID: 475278	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC
Facility ID: 475279	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC
Facility ID: 475280	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC
Facility ID: 475281	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC
Facility ID: 475282	Type: OFF-	API Number: -	Status: AC	Insp. Status: AC

Producing Well

Comment: PR	
Corrective Action:	Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 10/2/20 at approximately 1330 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Suckla Brown Unit 17</p> <p>Company Name- KPK</p> <p>API- 05-123-09485</p> <p>In Weld County Colorado.</p> <p>While there, I observed Producing well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil by flowline manifold appears to be leaking see pictures 1,2</p> <p>Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. 10/1/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection I contacted emergency number on wellsite and informed KPK representative of possible issue on location.</p> <p>This is a summary of inspection report.</p>	medinaj	10/01/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402507916	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5266318
699501739	Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5266308