

Inspection Photos
Operator: Catamount Energy
API: 067-05304
Date: 10/13/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with smooth brome, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of revegetation in the northwestern fill slope, that appears to be stabilized at this time.




Photo 4. View of Russian knapweeds in the northern project area. Approximately 1000 individuals remain.



Photo 5. View of reference area vegetation comprised of pinyon and juniper woodland with and understory of sagebrush, squirreltail, Indian ricegrass, and mixed forbs.



Photo 6. View of farm gates already open while entering and leaving location.