

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: 4' barb wire

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: electric

Corrective Action:

Date: _____

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: _____

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date: _____

Type: Bradenhead # 1

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 242561 Type: WELL API Number: 123-10352 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast and breezy. At time of inspection some weeds were growing in side fence, may need to addressed soon. At time of inspection downed tree was blocking lease road, however was able to take alternate route to get inside location.</p>	medinaj	10/16/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501779	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272260