

Western Operating Company, Starlin 42-5  
121-10890

Inspection #688308792

10/15/2020

Routine Inspection



Colorado Oil and Gas Conservation Commission  
40.08968, -103.21347, 4547.2ft, 164°  
10/15/2020 02:11:50 PM






Colorado Oil and Gas Conservation Commission  
40.08254, -103.21356, 4540.7ft, 187°  
10/15/2020 02:13:43 PM





Colorado Oil and Gas Conservation Commission  
40.08254, -103.21356, 4540.7ft, 186°  
10/15/2020 02:13:48 PM



Colorado Oil and Gas Conservation Commission  
40.08251, -103.21359, 4553.8ft, 348°  
10/15/2020 02:14:20 PM






Colorado Oil and Gas Conservation Commission  
40.08249, -103.21352, 4547.2ft, 315°  
10/15/2020 02:14:00 PM



Colorado Oil and Gas Conservation Commission  
40.08231, -103.21384, 4553.8ft, 236°  
10/15/2020 02:14:50 PM





Colorado Oil and Gas Conservation Commission  
40.08231, -103.21388, 4557.1ft, 222  
10/15/2020 02:15:02 PM





Colorado Oil and Gas Conservation Commission  
40.08231, -103.21384, 4553.8ft, 229°  
10/15/2020 02:14:53 PM





Colorado Oil and Gas Conservation Commission  
40.08233, -103.21385, 4557.1ft, 348°  
10/15/2020 02:15:06 PM





Colorado Oil and Gas Conservation Commission  
40.11838, -103.19727, 4534.1ft, 314°  
10/15/2020 02:37:49 PM

**ABB**

$\mu$ FLO 6213

Starlin 42-5 #422



**TOTALFLOW**  
MEASUREMENT CONTROL SYSTEMS

Colorado Oil and Gas Conservation Commission  
40.11829, -103.19717, 4547.2ft, 154°  
10/15/2020 02:37:10 PM