

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2020

Submitted Date:

10/19/2020

Document Number:

698100198**FIELD INSPECTION FORM**Loc ID 334413 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
,		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478244	SPILL OR RELEASE	AC	10/13/2020		-	SGV 2I	EI

General Comment:

COGCC Environmental Inspection, follow-up to Operator's Initial Spill/Release Report (eForm 19 doc #402509155 for Spill/Release ID #478244). Weather conditions during inspection were sunny with a temperature of 35 degrees Fahrenheit.

Operator's Initial Spill/Release report indicates that operator is in the process of determining the extent of contamination and cause of release. A Supplemental Spill/Release report is due within 10 calendar days of the reported Discovery Date, 10/10/2020.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	300 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	Produced water and Condensate (SOUR)
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Adequate
Comment:	No holes or tears were observed in visible portion of secondary containment liner on inspection date. Vegetation growth was observed inside north end of secondary containment area. See photos.			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected FacilitiesFacility ID: 478244 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698100199	20201016 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272830