

Inspection Photos
Operator: Hilcorp Energy
API: 067-09340
Date: 10/15/2020



Photo 1. View of the project area from the southern edge facing center. Revegetation is progressing with sand dropseed and western wheatgrass.



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of the reference area comprised of sagebrush shrubland and gambel oak shrubland mosaic with understory of grasses and forbs such as blue grama, sand dropseed, and snakeweed.



View of closed gates after crossing used to access location.