

Inspection Photos

Location Name: LARAMIE ENERGY LLC Homer Deep Unit /15-23 Pad

Location ID: 311760



Photo #2045 from entrance to location.



Photo #2047 Rill erosion

Inspection Photos

Location Name: LARAMIE ENERGY LLC Homer Deep Unit /15-23 Pad

Location ID: 311760



Photo #2048 Rill erosion around check dam.



Photo #2049 Rill erosion

Inspection Photos

Location Name: LARAMIE ENERGY LLC Homer Deep Unit /15-23 Pad

Location ID: 311760



Photo #2046 Sediment trap is full.