

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-22-69S98W /22NENW

Location ID: 312650



Photo #2061 from entrance to location.



Photo #1076 form inspection #699800992 conducted on 4/27/20.

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-22-69S98W /22NENW

Location ID: 312650



**Photo #1077 form inspection #699800992 conducted on 4/27/20.**



**Photo #2062 Unused equipment.**

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-22-69S98W /22NENW

Location ID: 312650



**Photo #1074 form inspection #699800992 conducted on 4/27/20.**



**Photo #1075 form inspection #699800992 conducted on 4/27/20.**

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-22-69S98W /22NENW

Location ID: 312650



Photo #2063 Debris on location.