

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/20/2020

Submitted Date:

10/21/2020

Document Number:

699801962**FIELD INSPECTION FORM**Loc ID 312648 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jordan, Reid		maralextechjr@gmail.com	
, BLM		jbyers@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Graves, Jim		mrinc20@maralexinc.com	
, Engineering		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222082	WELL	SI	12/30/2010	GW	077-08684	SULFUR GULCH 9-98-21 1	SI

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 10/20/20 at approximately 14:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC SULFUR GULCH 9-98-21-69S98W /21NENE, Location #312648 in Mesa County Colorado.

Refer to document #699800990 inspection conducted on 4/27/20. Not all previous corrective actions have not been completed.

During this inspection the following possible compliance issues were observed: Battery sign is not posted on location. With a previous corrective action date of 7/27/20. No emergency contact information posted on location. With a previous corrective action date of 7/27/20. Multiple places with debris on location. See photo #1064, #1065 and #2065. With a previous corrective action date of 5/11/20. Tank has been disconnected. See Photo #1068 and #2066 with a previous corrective action date of 7/27/20. Multiple flow lines not LO/TO. See photo #1069 and #1070 and #2067. With a previous corrective action date of 7/27/20. MIT required on well. With a previous corrective action date of 7/27/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Type	BATTERY			
Comment:	Battery sign is not posted on location.			
Corrective Action:	Within sixty (60) days after the installation of a battery, a permanent sign shall be located at the battery. Install battery sign on location.		Date:	07/27/2020
Emergency Contact Number:				
Comment:	No emergency contact information posted on location.			
Corrective Action:	Battery and or wellhead sign shall provide a phone number for local emergency services. Post emergency contact information.			Date: 07/28/2020
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Multiple places with debris on location. See photo #1064, #1065 and #2065			
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.		Date:	05/11/2020
Type	UNUSED EQUIPMENT			
Comment:	Multiple flow lines not LO/TO. See photo #1069, #1070 and #2067			
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Lock out tag out or plug flowline riser.		Date:	07/27/2020
Type	STORAGE OF SUPL			
Comment:	Tank has been disconnected. See Photo #1068 and #2066			
Corrective Action:	Production facilities, shall be kept free of equipment supplies not necessary for use on that lease. Remove Tank from location.		Date:	07/27/2020
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Hog panels			
Corrective Action:			Date:	
<b>Equipment:</b>				
Type: Pump Jack	# 1			corrective date

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 222082 Type: WELL API Number: 077-08684 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last produced May 2009. MIT last preformed 9/24/14.Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well.Date: 07/27/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801963	Photos for Insp. #699801962	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274426">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274426</a>