

# Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 10/19/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020

## Inspection Photos



**Photo 1.** Facing northeast toward the location. The yellow tank has been removed however, other unused equipment has not been removed and interim reclamation has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020

## Inspection Photos



**Photo 2.** Facing northeast toward the location. This red tank shown by arrow has not been removed and this area has not been reclaimed. Previous corrective actions have not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020



## Inspection Photos



**Photo 3.** Facing east at the location. There is 5 frac tanks staged that remain. The tanks have not been removed since previous inspection. Previous corrective actions have not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020



## Inspection Photos



**Photo 4.** Facing north at the location. There is erosion occurring of the disturbed pad site which is filling in the perimeter wattles.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020

## Inspection Photos



**Photo 5.** Facing northeast towards the frac-tanks stored at the location. It appears this area is pooling stormwater and is causing erosion shown in previous photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020



## Inspection Photos



**Photo 6.** Facing southwest behind the frac tanks. The wattles have filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020



## Inspection Photos



**Photo 7.** Facing north at the location. Disturbed areas around the location have not been reclaimed and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020



## Inspection Photos



**Photo 8.** Facing southwest at the location and toward the production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020

## Inspection Photos



**Photo 9.** Facing southeast at the location and toward the production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020



## Inspection Photos



**Photo 10.** Facing southwest toward the topsoil pile which are not maintained and protected from degradation and weed infestation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020



## Inspection Photos



**Photo 11.** Facing toward the topsoil pile. The topsoil piles are not stabilized and protected. Topsoil piles have not been replaced for interim reclamation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020



## Inspection Photos



**Photo 12.** Facing northeast toward the location. The unused tanks need to be removed. This area needs to be recontoured and reclaimed. Previous corrective actions have not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020

## Inspection Photos



**Photo 13.** Facing east toward the location. The unused tanks need to be removed. This area needs to be recontoured and reclaimed. Previous corrective actions have not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 10/19/2020