

Inspection Photos

Operator: BP America
API: 067-07175
Date: 10/20/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, sand dropseed, and smooth brome. Stormwater controls appear to be functioning at this time.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with gambel oak, western wheatgrass, prairie junegrass, and Oregon grape in the understory.