

Inspection Photos

Operator: Crescent Point Energy
API: 113-06220
Date: 10/20/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of culvert outlet along the access road that is not stabilized and above grade.



Photo 3. View of another culvert outlet needing stabilization.



Photo 4. Closeup view of culvert outlet needing stabilization, where you can see erosional down-cutting starting to occur.



Photo 4. View of reference area vegetation comprised of greasewood and sagebrush shrubland with blue grama, prickly pear, and *Chaetopappa* spp.