

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/21/2020

Submitted Date:

10/21/2020

Document Number:

699501788**FIELD INSPECTION FORM**
 Loc ID 454520 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454516	WELL	PR	02/10/2019	OW	123-46588	ENGLISH FARMS 8-12HZ	PR
454517	WELL	PR	11/01/2019	OW	123-46589	ENGLISH FARMS 8-8HZ	PR
454518	WELL	PR	02/24/2019	OW	123-46590	ENGLISH FARMS 8-10HZ	PR
454521	WELL	PR	02/10/2019	OW	123-46591	ENGLISH FARMS 8-13HZ	PR
454522	WELL	PR	02/20/2019	OW	123-46592	ENGLISH FARMS 8-11HZ	PR
454523	WELL	PR	02/22/2019	OW	123-46593	ENGLISH FARMS 8-9HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

1

Comment: Automation

Corrective Action:

Date:

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Type: Bradenhead

6

Comment: All plumbed with stainless steel cap line to annulus.

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 454516 Type: WELL API Number: 123-46588 Status: PR Insp. Status: PRFacility ID: 454517 Type: WELL API Number: 123-46589 Status: PR Insp. Status: PRFacility ID: 454518 Type: WELL API Number: 123-46590 Status: PR Insp. Status: PRFacility ID: 454521 Type: WELL API Number: 123-46591 Status: PR Insp. Status: PRFacility ID: 454522 Type: WELL API Number: 123-46592 Status: PR Insp. Status: PRFacility ID: 454523 Type: WELL API Number: 123-46593 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Chemical injection cube with IOT and automation.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast and calm.	medinaj	10/21/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501789	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5275309