

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: Weeds growing in tank berm, and inside flowline manifold.

Corrective Action: Comply with 603 f.

Date: 11/15/2020

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: fabricated fencing around manifold.

Corrective Action:

Date:

Equipment:

corrective date

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: gas motor

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,
Comment:	<input type="text"/>				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shares containment with oil tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
Date:			

Flaring:

Type		
Comment:		
Corrective Action:		
Date:		

Inspected Facilities

Facility ID: 202480 Type: WELL API Number: 001-07885 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 10/15/20 at approximately 1145 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Champlin 248 Amoco C 2 Company Name- Renegade oil and gas API- 05-001-07885 In Adams County Colorado. While there, I observed SI well. During this inspection the following possible compliance issues were observed: Weeds growing around wellhead see pic 1 Comply with 603 f. 11/15/20 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	10/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402512509	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271628
699501765	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5271606