

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2020

Submitted Date:

10/14/2020

Document Number:

701100596

FIELD INSPECTION FORM

Loc ID 335510 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|---------------------------------------|---------------------------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 296803 | WELL | PR | 08/17/2010 | GW | 045-16146 | 697-28C 23 | PR |
| 296804 | WELL | PR | 08/17/2010 | GW | 045-16147 | 697-28A 18 | PR |
| 298051 | WELL | PR | 08/17/2010 | GW | 045-17044 | 697-33A 11 | PR |

General Comment:

This is a summary of inspection report performed by Mike Longworth at CAERUS PICEANCE LLC, 697-28C-66S97W 28NESW, Location ID: 335510
During this inspection the following possible compliance issues were observed:
1 - Well sign is falling off well.
Install sign to comply with Rule 210.b.
CA Date 01/15/2020

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|---|--|------------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well sign is falling off well. | | |
| Corrective Action: | Install sign to comply with Rule 210.e. | | Date: 01/15/2021 |
| Type | BATTERY | | |
| Comment: | Hydro mulch on Battery sign. | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|-----|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|-------|--|-------|
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|--|-------|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | |
|----------------------------|-----------------------|------------------------------|---|
| Facility ID: <u>296803</u> | Type: <u>WELL</u> | API Number: <u>045-16146</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: | <u>Producing well</u> | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>296804</u> | Type: <u>WELL</u> | API Number: <u>045-16147</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: | <u>Producing well</u> | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>298051</u> | Type: <u>WELL</u> | API Number: <u>045-17044</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: | <u>Producing well</u> | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Pass | |
| Berms | Pass | | | | | |
| Compaction | Pass | | | | | |
| Gradient Terraces | Pass | | | | | |
| Gravel | Pass | | | | | |
| Hydro Mulch | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 402511464 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5270785 |
| 701100597 | Inspection 701100596 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5270783 |