

Inspection Photos

API: 043-40006

Operator: JAVERNICK OIL

Inspection Date: 10/19/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40006 | Date: 10/19/2020

Inspection Photos



Photo 1. Facing south toward the location. There is large cobble size gravel that remains on the former access road shown in photo. Areas of the location are bare of vegetation and have not been reclaimed. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40006 | Date: 10/19/2020

Inspection Photos



Photo 2. Facing south toward the location. Areas of the location are bare of vegetation and have not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40006 | Date: 10/19/2020

Inspection Photos



Photo 3. The cement blocks and anchors have been removed since previous inspection from rea shown in photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40006 | Date: 10/19/2020

Inspection Photos



Photo 4. Facing north at the location. Areas of the location are bare of vegetation and have not been reclaimed. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40006 | Date: 10/19/2020