

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2020

Submitted Date:

10/22/2020

Document Number:

697002282

FIELD INSPECTION FORM

Loc ID 328418 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 248169 | WELL | PR | 01/01/2020 | OW | 123-15967 | GOLLNER O 27-02 | PR |

General Comment:

[FIRR document #402516026](#)

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|-------------------------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Lease road entrance | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

| Spills: | | | | |
|----------------|------|--------|--|--|
| Type | Area | Volume | | |
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Fencing/: | | | |
|--------------------|-----------------------------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | Livestock fencing | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|---------------------------|---|-------|-----------------|
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead valve is exposed at surface. | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |

| | | |
|--|-----|-------|
| Comment: Automation array and two ECD scrubbers | | Date: |
| Corrective Action: | | Date: |
| Type: Emission Control Device | # 2 | |
| Comment: Pilots are on | | Date: |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 1 | |
| Comment: Calibration card noted in prior inspection document #697002218 has been updated. See attached photos. | | Date: |
| Corrective Action: | | Date: |
| Type: Pig Station | # 1 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 1 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 3 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------------------------|---|----------|--------------|---------|--------|
| PRODUCED WATER | 1 | <50 BBLS | PBV CONCRETE | | , |
| Comment: 48 bbls | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | Date: | | |
| Corrective Action: | | Date: | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 1 | 400 BBLS | STEEL AST | | , |
| Comment: | | Date: | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|-----------------|----------|
| Condition | Adequate |
| Other (Content) | |

| | |
|------------------|--|
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| Yes/No | NO | | | | |
|--------------------|----|--|--|-------|--|
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Flaring:

| | | | | | |
|--------------------|--|--|--|-------|--|
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Inspected Facilities

Facility ID: 248169 Type: WELL API Number: 123-15967 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 697002283 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5275997 |