



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
	Comment: Panel		
Corrective Action:		Date:	

**Equipment:**

				corrective date
Type: Plunger Lift	# 1			
Comment:	<input style="width: 95%;" type="text"/>			
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	<input style="width: 95%;" type="text"/>			
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 295781 Type: WELL API Number: 123-25807 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
This is a follow up inspection to previous inspection DOC#: 679603048. All previous corrective actions have been resolved. No new corrective actions were observed at the time of re-inspection. **Weather Conditions: cloudy, dry ground	santistb	10/23/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603428	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5276630">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5276630</a>