

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /15SWNE

Location ID: 334105



Photo #2107 from entrance to location.



Photo #2101 Multiple places with rill erosion.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /15SWNE

Location ID: 334105



**Photo #2104 Multiple places with rill erosion.**



**Photo #2105 Multiple places with rill erosion.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /15SWNE

Location ID: 334105



Photo #2106 culvert inlet



Photo #2098 culvert inlet

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /15SWNE

Location ID: 334105



Photo #2108 Approximate culvert locations.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /15SWNE

Location ID: 334105



Photo #2102 culvert outlet.



Photo #2103 2 to 3 feet deep gully erosion.