

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2020

Submitted Date:

10/16/2020

Document Number:

699801944

**FIELD INSPECTION FORM**

Loc ID: 312674      Inspector Name: De Paolo, Corey      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 6 Number of Comments  
 3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 96790  
 Name of Operator: WILLSOURCE ENTERPRISE LLC  
 Address: 730 17TH ST STE 712  
 City: DENVER      State: CO      Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Williams, Reed	(303) 575-9696	reed@willsourceenterprise.com	President
, Engineering		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263767	WELL	TA	12/01/2019	GW	077-08760	LITTLE BEAVER 1-20	TA

**General Comment:**

COGCC Inspection Report Summary  
 On Friday 10/16/20 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at WILLSOURCE ENTERPRISE LLC LITTLE BEAVER-69S90W /20NENE, Location #312674 in Mesa County Colorado.  
 Refer to document #699801358 inspection conducted on 6/30/20. Not all corrective actions have been completed.  
 During this inspection the following possible compliance issues were observed: Unused equipment. See photo #1439 and #2039 with a previous corrective action date of 9/30/20. Multiple places with debris on location. See photo #2037 and #2038 with a corrective action date of 10/30/20. Well overdue for MIT. With a previous corrective action date of 9/30/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	<input type="text" value="911"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Multiple places with debris on location. See photo #2037 and #2038		
Corrective Action:	Production facilities, shall be kept free of debris. Remove debris from location	Date:	10/30/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment. See photo #1439 and #2039		
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove all unused equipment from location.	Date:	09/30/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type:	Bird Protectors	# 1	corrective date
Comment:			
Corrective Action:			Date:
Type:	Deadman # & Marked	# 6	
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 263767 Type: WELL API Number: 077-08760 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last MIT preformed 11/6/2014.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed.Preform MIT on well.

Date: 09/30/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Berms				
		Gravel				
		Culverts				
		Ditches				
Berms						
Ditches						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402513540	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272568</a>
699801945	Photos for Insp. #699801944	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272566</a>