

Inspection Photos

API: 055-06309

Operator: ALTA MESA SERVICES LP

Inspection Date: 10/23/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 1. Facing north toward the location. The access road has not been reclaimed. The cattle guard and gates remain and the perimeter of the location is fenced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 2. Facing northwest toward the location. This portion of the location has not been recontoured and reclaimed. There are undesirable and noxious weeds growing throughout the location which have not been controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 3. Facing southwest toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 4. Facing northwest at the location. There are dead tree debris that remain at the location which have not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 5. There is undesirable weeds throughout the location which have not been controlled. The desirable vegetation is not establishing and reseeding needs to be performed. The weed debris needs to be cut and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 6. Facing northwest at the west side of the location. There are numerous noxious weeds growing throughout the location shown by red arrow which points to Scotch thistle List B noxious weed. Other weeds observed were Cheat grass, Russian thistle, Common mullein, Kochia, Mustard.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 7. Facing east at the north side of the location. The dark brown vegetation is undesirable weeds, Russian thistle. The weed debris needs to be cut and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 8. Facing north at the location. This portion of the location was not reclaimed and gravel remained on this flat portion. There are undesirable weeds throughout this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020

Inspection Photos



Photo 9. Facing southwest at the east side of the location. This area of the location has not been recontoured and reclaimed and gravel remains within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 10/23/2020