

Inspection Photos

Operator: BP America
API: 067-08655
Date: 10/22/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Berm is installed, bare/weedy soils on fill slopes remain.



Photo 3. View of the western project area from the southwestern corner facing northward. Berm is installed, bare soils on fill slopes remain.



Photo 4. View of Canada thistles and musk thistle that remains within the project area. Canada thistles are partially treated but persist. Scattered musk thistle rosettes observed (inset).



Photo 5. View of reference area comprised of irrigated grass field.



Photo 6. View of closed gate after leaving location.