

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/26/2020

Submitted Date:

10/26/2020

Document Number:

693503711

FIELD INSPECTION FORM

Loc ID 431161 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431166	WELL	PR	03/01/2020	SI	123-36449	BADGER 22N-3HZ	PR
431167	WELL	PR	03/01/2020	SI	123-36450	BADGER 12N-3HZ	PR
431168	WELL	PR	05/03/2020	OW	123-36451	BUFFALO 14C-15HZ	PR
431169	WELL	PR	04/18/2020	OW	123-36452	BUFFALO STATE 34N-15HZ	PR
431170	WELL	PR	03/01/2020	SI	123-36453	BADGER 12C-3HZ	PR
431171	WELL	PR	03/01/2020	SI	123-36454	BUFFALO 35C-15HZ	PR
431172	WELL	PR	05/06/2020	OW	123-36455	BUFFALO 14N-15HZ	PR
431173	WELL	PR	05/03/2020	SI	123-36456	BADGER 22C-3HZ	PR
431174	WELL	PR	05/05/2020	OW	123-36457	BADGER 25N-3HZ	PR
431175	WELL	PR	05/06/2020	SI	123-36458	BADGER 11N-3HZ	PR
431176	WELL	PR	03/01/2020	SI	123-36459	BUFFALO 13C-15HZ	PR
431177	WELL	PR	05/04/2020	OW	123-36460	BUFFALO 36C-15HZ	PR
431178	WELL	PR	04/20/2020	OW	123-36461	BUFFALO 13N-15HZ	PR
431179	WELL	PR	04/29/2020	SI	123-36462	BUFFALO 35N-15HZ	PR
431180	WELL	PR		SI	123-36463	BADGER STATE 32C-3HZ	PR
431181	WELL	PR	05/03/2020	OW	123-36464	BADGER 11C-3HZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Steel rod fence		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 16		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	431166	Type:	WELL	API Number:	123-36449	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	431167	Type:	WELL	API Number:	123-36450	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	431168	Type:	WELL	API Number:	123-36451	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	431169	Type:	WELL	API Number:	123-36452	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	431170	Type:	WELL	API Number:	123-36453	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	431171	Type:	WELL	API Number:	123-36454	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	431172	Type:	WELL	API Number:	123-36455	Status:	PR	Insp. Status:	PR
Complaint									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	431173	Type:	WELL	API Number:	123-36456	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Facility ID:	431174	Type:	WELL	API Number:	123-36457	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR		
Corrective Action:		Date:	

Facility ID:	431175	Type:	WELL	API Number:	123-36458	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR		
Corrective Action:		Date:	

Facility ID:	431176	Type:	WELL	API Number:	123-36459	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR		
Corrective Action:		Date:	

Facility ID:	431177	Type:	WELL	API Number:	123-36460	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR		
Corrective Action:		Date:	

Facility ID:	431178	Type:	WELL	API Number:	123-36461	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR		
Corrective Action:		Date:	

Facility ID:	431179	Type:	WELL	API Number:	123-36462	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR		
Corrective Action:		Date:	

Facility ID:	431180	Type:	WELL	API Number:	123-36463	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Completion

Operation:	Preparation
Date Flowback:	
Contractor:	Ranger Rig 16
Comment:	Well previously started fracing but had to stop operations due to wireline parting form 5 A Doc#402500198 was submitted to the COGCC. At time of inspection crew is on site to fish wire line gun out of hole to prep for frac to complete hole on a unknown date. Company supervisor is Fernando Ortega. MSDS and safety plan are on site.
Corrective Action:	
Date:	

Facility ID: 431181	Type: WELL	API Number: 123-36464	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR	
Corrective Action:	Date:

COGCC Comments

Comment	User	Date
Routine inspection. At time of inspection it snowed the night befor.	silverr	10/26/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503712	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5277587