

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/26/2020

Submitted Date:

10/26/2020

Document Number:

693503716

FIELD INSPECTION FORM

Loc ID 335663 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242210	WELL	PA	12/13/2017	GW	123-10001	EDWARD P COSTIGAN 1	PA
278553	WELL	SI	03/01/2020	GW	123-23057	COSTIGAN 33-20	PA
301573	WELL	SI	09/01/2019	OW	123-30058	COSTIGAN 34-20	SI
301574	WELL	PA	03/27/2019	GW	123-30059	COSTIGAN 43-20	PA
301900	WELL	SI	03/01/2020	OW	123-30124	COSTIGAN 6-8-20	PA
414608	WELL	PR	06/01/2020	GW	123-30790	COSTIGAN 8-6-20	PR
417672	WELL	PR	08/01/2020	OW	123-31717	COSTIGAN 8-8-20	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Signs are on site but down due to rig work.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242210 Type: WELL API Number: 123-10001 Status: PA Insp. Status: PA

Facility ID: 278553 Type: WELL API Number: 123-23057 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: P&A Well is P&A Forms 42 Doc#40222965 and 6S Doc#402265108 are on file with the COGCC.

Corrective Action: _____ Date: _____

Facility ID: 301573 Type: WELL API Number: 123-30058 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 301574 Type: WELL API Number: 123-30059 Status: PA Insp. Status: PA

Facility ID: 301900 Type: WELL API Number: 123-30124 Status: SI Insp. Status: PA

Workover

Comment: At time of inspection crew is performing re-entry. Crew drilled out 752ft of cement set packer leaving well closed in overnight to see if presure build to find leak. This a Ensign rig #352 Supervisor is Derek Depee.

Corrective Action: _____ Date: _____

Facility ID: 414608 Type: WELL API Number: 123-30790 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 417672 Type: WELL API Number: 123-31717 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine inspection. At time of inspection crew had just shut down for day.</u>	silverr	10/26/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503717	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5277589