

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402481269

Date Received:

09/03/2020

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902084  
Inspection Date: 07/28/2020 FIR Submit Date: 08/04/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333494

Location Name: ARGENTA 34-10-M34N10W Number: 32NWSE County: LA PLATA  
Qtrqtr: NWSE Sec: 32 Twp: 34N Range: 10W Meridian: M  
Latitude: 37.144480 Longitude: -107.954750

FACILITY - API Number: 05-067-00 Facility ID: 291758

Facility Name: ARGENTA 34-10 Number: 32-2A  
Qtrqtr: NWSE Sec: 32 Twp: 34N Range: 10W Meridian: M  
Latitude: 37.144480 Longitude: -107.954750

CORRECTIVE ACTION:

**1**  CA# 141005

Corrective Action: -Clean and properly dispose of discharged material, conduct maintenance to prevent further discharge by 8/10/2020.

Date: 08/10/2020

Response: CA COMPLETED Date of Completion: 08/31/2020

Operator Comment: Red stained soil around water can was removed and new pit run material was installed

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**2**  CA# 141006

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 09/04/2020

Response: CA COMPLETED

Date of Completion: 08/31/2020

Operator Comment:

All wattles were removed and berms were built in their place

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Walker

Signed: \_\_\_\_\_

Title: Operation Regulatory Tech

Date: 9/3/2020 8:29:22 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402481269	FIR RESOLUTION SUBMITTED
402481274	Resolved Photos

Total Attach: 2 Files