

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/21/2020

Submitted Date:

10/21/2020

Document Number:

696302575**FIELD INSPECTION FORM**
 Loc ID 430127 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 LINCOLN STREET SUITE 4700City: DENVER State: CO Zip: 80290**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	Eastern Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430130	WELL	PR	05/22/2013	OW	123-36057	Razor 11-0241H	PR
435408	WELL	PR	06/26/2015	OW	123-38598	Razor 11H-0215A	PR
435411	WELL	PR	06/28/2015	OW	123-38601	Razor 11H-1415A	PR

General Comment:

This is an Field Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at Pumping Unit, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."	Date:	11/06/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Gas Lift Injection Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 430130 Type: WELL API Number: 123-36057 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 435408 Type: WELL API Number: 123-38598 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 435411 Type: WELL API Number: 123-38601 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Stained Soil at Pumping Unit	petrie	10/21/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402515552	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274638
696302576	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274636