

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/20/2020

Submitted Date:

10/20/2020

Document Number:

699801960

FIELD INSPECTION FORMLoc ID 312650 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, BLM		jbyers@blm.gov	
Graves, Jim		mrinc20@maralexinc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222085	WELL	SI	05/01/2012	GW	077-08687	SULFUR GULCH 9-98-22 1	SI

General Comment:**COGCC Inspection Report Summary**

On Tuesday 10/20/20 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted a follow up at MARALEX RESOURCES INC SULFUR GULCH 9-98-22-69S98W /22NENW, Location #312650 in Mesa County Colorado.

Refer to document #699800992 inspection conducted on 4/27/20. Not all corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Battery sign is not posted on location. With a previous corrective action date of 7/27/20. No emergency contact information posted on location. With a previous corrective action date of 7/27/20. Multiple places with unused equipment on location. See photo #1076, #1077 and #2062. With a previous corrective action date of 7/27/20. Multiple places with debris on location. See photo #1074, #1075 and #2063. With a previous corrective action date of 5/11/20. MIT required on well. With a previous corrective action date of 7/27/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign is not posted on location.		
Corrective Action:	Within sixty (60) days after the installation of a battery, a permanent sign shall be located at the battery. Install battery sign on location.		Date: 07/27/2020
Emergency Contact Number:			
Comment:	No emergency contact information posted on location.		
Corrective Action:	Battery and or wellhead sign shall provide a phone number for local emergency services. Post emergency contact information.		Date: 07/27/2020
Good Housekeeping:			
Type	DEBRIS		
Comment:	Multiple places with debris on location. See photo #1074, #1075 and #2063.		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.		Date: 05/11/2020
Type	UNUSED EQUIPMENT		
Comment:	Multiple places with unused equipment on location. See photo #1076, #1077 and #2062.		
Corrective Action:	Production facilities, shall be kept free of equipment supplies not necessary for use on that lease. Remove unused equipment from location.		Date: 07/27/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 222085 Type: WELL API Number: 077-08687 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well last produced June 2009. Last MIT preformed on 10/3/14Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well.Date: 07/27/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402515284	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274428
699801961	Photos for Insp. #699801960	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274425